



ASIASTAR

YBL6111H BUS MEDICAL STD 4X2 BVM DIES





Vue de face



Vue de profil



Feu de jour



Feu anti-brouillard LED



MOTORLAND

Logo ASI STAR

A close-up, low-angle shot of a white vehicle's side mirror. The mirror is black and mounted on a white arm. Below the mirror, there is an orange turn signal light. The vehicle's body is white with orange decorative stripes. The background is a clear blue sky.

MOTORLAND

Rétroviseur automatique avec clignotant



ML MOTORLAND

Serrure de sécurité portière



Bouton d'urgence externe



Clignotant LED

 MOTORLAND

Cage d'ascenseur

A close-up photograph of the rear of a white vehicle. The image focuses on the rear left side, showing a large, vertically oriented LED stop light with a red lens. Below it is a smaller, horizontally oriented LED light. To the right of the main light is a white plastic storage compartment with a silver latch. The vehicle is parked on a light-colored, textured surface, possibly gravel or sand, under a clear sky. A watermark "MOTORLAND" is visible across the center of the image.

MOTORLAND

Feu STOP arrière LED

YBL6111H

MOTORLAND

Série BUS



MOTORLAND

Lumière d'éclairage plaque d'immatriculation



Ascenseur



 **Xinder**

UVL LIFT 

www.xinder.cn
www.china-mobility

Ascenseur



MOTORLAND

Ascenseur



Ascenseur

MOTORLAND



Commande ascenseur



MOTORLAND

Ascenseur



Cage d'ascenseur



ML MOTORLAND

Moniteur ascenseur

A blue metal access ladder with yellow handrails and a control panel. The ladder is mounted on a blue metal frame. The control panel is located on the left side of the ladder and includes a key switch, a digital display, and a coiled cable. The ladder has three steps and a yellow handrail on the right side. The background is a blue metal wall.

M MOTORLAND

Escalier d'accès


 MOTORLAND



MOTORLAND

Royalstar 荣事达

Sortie d'air climatisation



Royalstar 荣事达

风幕机

Sortie d'air climatisation



M MOTORLAND

Sortie d'air climatisation



Sortie d'air climatisation

MOTORLAND

② 拉去塑料防护罩
Retirer le bouchier en plastique



仅供紧急出口
Sortie d'urgence uniquement

③ 旋转手柄并推出
Rotation de la poignée et déploiement



① 双向推开安全顶窗
Pousser la fenêtre supersonique de sécurité dans les deux sens



④ 从出口脱离危险
Hors de danger par la sortie



Sortie d'issue d'urgence



MOTORLAND

Sortie d'air climatisation



Haut-parleur

照明

消毒

MOTORLAND



Interrupteur

 MOTORLAND

Prise



ML MOTORLAND

Caméra interne



MCMCORN AND

Eclairage interne



Bureau d'accueil



Salle de soins



MOTORLAND

Salle de soins

The image shows the interior of a motorhome, specifically a care room. It features a white cabinet with a blue cushioned top, partially obscured by white curtains hanging from a metal rod. Blue curtains are also visible on the right side. The floor is blue, and the ceiling has recessed lights and ventilation fans. The text 'MOTORLAND' is overlaid in the center.

MOTORLAND

Salle de soins

A photograph of a medical examination room. In the center is a large, stainless steel examination table. To the left of the table are two black, adjustable medical stools with chrome bases. Behind the table, there is a white cabinet with drawers and a built-in refrigerator with the brand name 'KIPPIN' visible. A window with a light blue curtain is on the right wall. A white vertical pole with a rope and tassel hangs near the window. The floor is blue. A watermark 'MOTORLAND' is overlaid in the center of the image.

MOTORLAND

Bureau de consultations



Salle de consultations

The image shows the interior of a motorhome. In the center is a white storage cabinet with two glass doors, revealing shelves inside. Above the cabinet are two white overhead storage bins. To the left, a stainless steel sink with a chrome faucet is visible. The walls are white, and the ceiling is also white. A small security camera is mounted on the right wall. The text 'MOTORLAND' is overlaid in the center.

MOTORLAND

Armoire et coffre de rangement



MOTORLAND

Lavabo



MOTORLAND

Bouton d'action robinet



M MOTORLAND

Lavabo