

 **DONGFENG**

**RICH6 2.4L STD 5P
D/C 4x4 BVM ESS**







MOTORLAND



MOTORLAND



Vue de face



Vue de profil

MOTORLAND

Rétroviseur avec clignotant



Jante Alliage Roue 255 / 70 R16

MOTORLAND

Feux de jour LED



Boutons vitre électrique



MOTORLAND

Boutons réservoir/Réglage phare/contrôle stabilité

A close-up photograph of a car's interior. The central focus is a circular air vent with horizontal slats, set into a dark, textured leather-like surface. To the right, a portion of a tachometer is visible, showing a needle pointing to approximately 4.5 on a scale from 0 to 10. The needle has a red tip. The overall lighting is soft, highlighting the textures of the leather and the metallic finish of the vent.

M MOTORLAND

Sortie d'air climatisation




Réglage clignotants

MOTORLAND

Réglage essuie-glace




Tableau de bord



MOTORLAND

Volant multifonction



MOTORLAND

Clé de démarrage



Ecran 7 pouces bluetooth + carlife



Levier de vitesse/Boite manuelle



Tableau de bord



Eclairage interne



MOTORLAND

Accoudoir central

A close-up photograph of the driver's seat in a car. The seat is upholstered in dark grey leather with white stitching. The seat is mounted on a black plastic base that features a large, ergonomic manual adjustment lever on the right side. In the background, the center console with a gear shifter and handbrake is visible. A small yellow tag with the number '501' is attached to the dashboard area. The entire image is framed by a dark red border.

MOTORLAND

Réglage manuel siège conducteur

The image shows the front interior of a car. The seats are upholstered in black leather with white stitching. The center console has a gear shifter and handbrake. The dashboard and steering wheel are partially visible. A watermark logo is centered over the image.

M MOTORLAND

siège cuir