




SX5 1.5 L COMFORT 5P
4X2 BVM ESS



MOTORLAND



Vue de face



Vue de profil



Roues 215/65 R16

A close-up, black and white photograph of a car's side mirror. The mirror is sleek and aerodynamic, reflecting the surrounding environment. A watermark for 'MOTORLAND' is overlaid on the mirror's surface. The 'M' is stylized with a vertical line through it. The rest of the letters are in a simple, outlined font. Below the mirror, a small rectangular light strip is visible, containing several small, square light elements.

MOTORLAND

Rétroviseur réglable électroniquement

A close-up photograph of the rear camera and sensor assembly of a vehicle. The camera lens is a circular, clear lens with a black ring, mounted on a black plastic housing. To the left of the lens is a rectangular sensor area with a grid of small, dark, rectangular elements. The entire assembly is mounted on a black plastic frame. The background is a dark, metallic surface, likely the rear of the car. A red banner is at the bottom of the image.

MOTORLAND

Caméra de recul

A close-up photograph of a black car's trunk handle. The handle is a rectangular, recessed button with a silver-colored metal frame. The Motorland logo, consisting of a stylized 'M' and 'L' inside a circle, is positioned to the left of the word 'MOTORLAND' which is written in a clean, sans-serif, uppercase font. The car's body is black and shows some signs of wear and dirt. The background is blurred, showing a white wall and a white car.

 MOTORLAND

Ouverture du coffre électrique



ML MOTORLAND

Poignée à verrouillage centralisé



Boutons vitre électrique



MOTORLAND

Sortie d'air climatisation



Réglage de phares



Réglage essuie-glace



Tableau de bord



Système climatisation



MOTORLAND

Écran tactile



Levier de vitesse avec boite manuelle



Volant uréthane



Tableau de bord

A close-up photograph of the interior of a car, specifically the center console area. The storage compartment is open, revealing a black plastic interior with a textured floor. The surrounding seats are upholstered in a grey fabric with a fine, repeating pattern and orange stitching. A black leather gear shift boot is visible on the right side of the console. A black plastic panel with a silver latch is on the left. A red rectangular button is visible on the right side of the console. The text 'MOTORLAND' is overlaid in the center of the image.

MOTORLAND

Boite de rangement

A close-up photograph of a car's interior, focusing on the central console and gear shift. The gear shift is a black leather-wrapped lever with a silver-colored metal knob, positioned on the left side of the frame. The central console is a large, black, leather-upholstered armrest with a red stitching detail along its edge. The surrounding seats are upholstered in a dark gray, textured fabric with red stitching. The overall aesthetic is modern and sporty.

MOTORLAND

Accoudoir central



MOTORLAND

Eclairage



Prise 12V + Port USB

The image shows the front interior of a car. The driver's seat and front passenger seat are upholstered in black fabric with a fine, woven texture. Red stitching is visible along the edges of the seat cushions, backrests, and headrests. The center console between the seats has a black leather-like armrest and two cupholders. The gear shift is located to the right of the center console. The dashboard and steering wheel are partially visible on the right side of the frame. The car's windows show a bright, clear sky outside.

MOTORLAND

Siège tissu



Vue arrière