



M29-1100Z 1.5L STD 2P 7m3
TRANSPORT DE MARCHANDISES
4X2 BVM ESS





Vue de face



Vue de profil



Phare de projection à quatre lampes

 MOTORLAND

Rétroviseur sans clignotant



MOTORLAND

Caméra de recul



M MOTORLAND

Poignée à verrouillage clé

ML MOTORLAND

Boutons vitre électrique



Réglage de phares



Réglage phare + clignotant



MOTORLAND

Réglage essuie-glace



Volant cuir + commande vocale



MOTORLAND

Clé de démarrage



Tableau de bord

A close-up photograph of a car's interior dashboard. The dashboard is covered in black leather with a pebbled texture. On the left side, there is a rectangular air vent with a silver-colored frame and horizontal slats. To the right of the vent, a portion of a circular instrument cluster is visible, showing a tachometer with a needle and the number '5' and 'r/min'. The word 'MOTORLAND' is overlaid in a white, outlined, sans-serif font across the center of the image. A small white arrow points from the first 'M' in 'MOTORLAND' towards the air vent.

MOTORLAND

Sortie d'air climatisation



Siège tissu

The image shows the interior of a white van. The walls are white with some black mesh panels. The floor is black with a white mesh pattern. A white plastic component is visible in the center of the floor. The ceiling is white with some black components. The overall appearance is clean and modern.

M MOTORLAND

Intérieur du Van



Ouverture arrière



Vue arrière