



**RICH 6 2.4 L STD 5P
D/C 4X4 BVM ESS**







Vue de face



Vue de profil



Roues 255 / 70 R16



Phares LED



Rétroviseurs extérieurs couleur carrosserie – électriques ajustables




Poignée à verrouillage centralisé



Boutons vitre électrique

MOTORLAND



Réglage de phares



MOTORLAND

Sortie d'air climatisation



ML MOTORLAND

Ouverture du capôt



Réglage phare + clignotant



Réglage essuie-glace



Volant cuir multifonction avec contrôle audio



Ecran 7 pouces bluetooth + carlife



Tableau de bord

A close-up photograph of a car's interior, focusing on the start/stop button. The button is circular, silver-colored, and set into a black leather dashboard with a pebbled texture. The button has a small slot at the top and the words "START", "STOP", and "ENGINE" printed on it. A silver gear shift lever is visible in the lower-left foreground. To the right, a portion of a digital display screen is visible, showing the number "87". The entire image is framed by a dark red border.

ML MOTORLAND

Bouton START & STOP

MOTORLAND

Commutateur de mode de conduite

A close-up photograph of a car's interior, focusing on the manual gear shift lever. The lever has a black leather boot with white stitching and a silver-colored metal shaft. The knob is covered in black leather with a textured pattern. To the left of the lever, there is a silver-colored rotary knob with markings for '2WD', '4x4', and '4x4L'. Above this knob are several rectangular buttons and a circular dial. The background shows the car's dashboard and center console with various controls and a door handle.

M MOTORLAND

Levier de vitesse avec boîte manuelle



Tableau de bord



MOTORLAND

Eclairage



MOTORLAND

Accoudoir central

A close-up photograph of a car's interior, specifically the center console. The console is upholstered in black leather with white stitching. The storage compartment is open, revealing a black plastic interior. A black plastic lid is propped open, showing its hinge mechanism. The surrounding seats are also upholstered in black leather with white stitching. A portion of a seatbelt with an orange buckle is visible on the right side of the frame.

MOTORLAND

Boite de rangement

A close-up photograph of the front interior of a car. The seats are upholstered in black leather with prominent white contrast stitching along the seams and edges. The center console is visible between the seats, featuring a gear shifter and handbrake. The background shows the steering wheel and dashboard area, all in a dark, cohesive color scheme. The overall lighting is bright, highlighting the texture of the leather.

M MOTORLAND

Siège cuir noir



Vue arrière